T-ISS B.V.

Hereby appoints

Pacific Safety Agency Pte Ltd

1 Sunview Road, #01-39 Eco-Tech @ Sunview, Singapore

Engineer: Ariharan Kirisnan

As its authorized service partner for T-ISS release hooks

In compliance with the requirements of IMO resolution MSC. 402(96) and MSC404(96) to inspect and service the following T-ISS Release hooks:

T-ISS PX-01, PX-02 and PX-03

All T-ISS Release hooks require a service pack to be installed, during the 5 yearly service. The service pack contains all wear-parts which need to be replaced an a Certificate of Serviceability (COSY) for that specific hook.

Authorization valid from 01/01/2026 to 31/12/2026

T-ISS Safety Suppliers Zoetermeer / Dinxperlo The Netherlands www.t-iss.com

Grietke Huls
Inside Sales

T-ISS BV
Helmkamp 56
7091 HR Dinxperlo
The Netherlands

T +31 (0) 315 65 60 60
F +31 (0) 315 65 60 63
E info@t-iss.com
I t-iss.com

Chamber of Commerce Arnhem
Number: 09162172
Vat nr.: NL 819298360B01
EORI nr.: NL 819298360

Bankname: ABN-AMRO Bank
Bankaccountnumber:59.94.28.635
BIC-code:ABNANL2A
IBAN nr.:NL33 ABNA 0599 4286 35

QUALITY SYSTEM CERTIFICATION DNV ISO 9001